

Vista III OS Update
Version 3.03
Release Date: 7/13/2009

Changes in this update:

1. Corrected a rare communications issue.
 - a. A short to ground on the Comm B line could cause a node to tie up the communications network in such a way that communications may hang until power is reset.
 - b. In normal operations, shorting this line to ground will cause the nodes to stop communicating to protect the communications chip, but once the short has been removed, communication should resume normally.
 - c. This modification will allow the node to resume communication once the error condition has been resolved.