

V-MUX Diagnostics Release Notes

Version 1.4.2

Released: 07/14/2010

This announcement is to inform you that Weldon has released a new version of the V-MUX Diagnostics application, version 1.4.2. The software is available on the Weldon website, www.weldoninc.com in the Software Updates section.

Feature Additions

1. None

Code Fixes

1. File FXMAPS.MDB renamed to FXMAPS.DAV
 - a. This is being done to correct a security related issue that some users would run into when installing V-MUX Diagnostics for the first time.
 - b. If you already have V-MUX Diagnostics v1.4.1 installed, there is no reason to upgrade to this version.

As with all our software updates, Weldon tries to ensure that no software bugs are introduced. We do however recommend testing the software using your binaries to ensure that we have not changed functionality that your designs require in any way.